

You are gonna need to weld up your old trunion holes.
Also you might run into a small problem with the front trunion catch hole.













